

THINK TECHSMART® FIRST

TechSmart® Electronic Throttle Bodies

The Problem: Electronic throttle bodies have high failure rates. When the original fails, it can affect a vehicle's power, fuel economy, and drivability.

Our Response: Meeting the demand for high-quality replacements, TechSmart's line of Electronic Throttle Bodies includes more than 130 direct-replacement units and covers more than 65 million VIO. To ensure quality and reliability, each unit is 100% new, never remanufactured. Plus, with our units, you won't encounter comebacks due to worn items in a partial rebuild.

100% NEW NOT REMAN

Undergoes extensive testing to ensure quality and reliability out of the box



New, never remanufactured, which maximizes performance and extends service life

TechSmart® Tip: Certain units require a factory relearn procedure, so remember to follow the OE service manual when performing the replacement.

S20120
Chrysler 2010-06
Dodge 2011-05
VIO over 1.9 Million

Superior Testing, Extensive Coverage

TechSmart's Electronic Throttle Bodies undergo extensive in-house testing at SMP's engineering department in Long Island City, NY. There, our engineers look at flow tests and make sure each unit meets our high performance standards. The result is a high-quality replacement with coverage for an array of domestic and import vehicles, including but not limited to **Audi/VW, BMW, Ford, Toyota, and GM.**



TechSmart® engineer performing TPS output test



ARE YOU TECHSMART®?

