

# THINK TECHSMART® FIRST


## TechSmart® High Pressure Fuel Pump Cam Follower



TechSmart® now offers a high-quality direct replacement High Pressure Fuel Pump Cam Follower for 2013-2006 VW/Audi 2.0T.



The low-friction coating on the original units can wear down over time causing excess friction against the cam lobe and high-pressure fuel pump plunger. This can lead to extreme engine damage and an expensive repair. Checking and replacing the cam follower with the TechSmart® T48001 will save money in the long run.




Catastrophic Failure



VW/Audi 2.0T 2013-06  
VIO over 1.0 Million

New  
TechSmart®  
T48001



ARE YOU TECHSMART®?

