



# New Parts Spotlight

## June 2016

### Transfer Case Gear Repair Kit

#### New Product Category

TechSmart's new Transfer Case Gear Repair Kit comes complete with everything you need to replace only the failed transfer case motor gear instead of the entire assembly. Providing a re-engineered alternative to the plastic OE gear, our kit includes an upgraded metal gear that better protects against wearing and breaking. The plastic OE gear is a common failure for certain BMW applications between 80,000 and 120,000 miles.



F52001  
BMW 2010-04  
VIO Over 250,000

### Windshield Wiper Motor

#### New Product Category

Faulty windshield wiper motors can cause driving issues during inclement weather. To provide high-quality replacements for this important safety category, TechSmart has introduced a new line of Windshield Wiper Motors for Hyundai and Kia applications. Each one is an Exact-Match, Direct-Fit OE replacement to ensure proper fit, form, and function.



Z94000  
Hyundai Sonata 2010-06  
VIO Over 580,000



Z94006  
Hyundai Santa Fe 2006-01  
VIO Over 390,000



Z94011  
Kia Sorento 2009-03  
VIO Over 280,000

## Accelerator Pedal Sensor Repair Kit

*1 New SKU Available*



G92005  
Chevy Trucks 2002-94  
VIO Over 5.2 Million

## Air Door Actuator

*5 New SKUs Available*



F04053  
Chevrolet Express 2015-03  
GMC Savana 2015-03  
VIO Over 1.1 Million

## Air Suspension Solenoid

*1 New SKU Available*



G35003  
Ford Expedition 2006-03  
Lincoln Navigator 2006-03  
VIO Over 660,000

## Electronic Throttle Body

*1 New SKU Available*



S20121  
Lexus ES300 2003-01  
VIO Over 130,000

## Engine Variable Valve Timing Spool

*2 New SKUs Available*



F10305  
Honda Civic 2005-96  
Honda Civic del Sol  
1997-96  
VIO Over 2.0 Million

## Headlight Level Sensor

*7 New SKUs Available*



B71107  
Mazda 3 2015-14  
Mazda 6 2015-14  
Mazda CX-5 2015-13  
VIO Over 530,000