

THINK TECHSMART® FIRST

TechSmart® Ignition Coil Wiring Harness Repair Kit

The ignition coil supplies the voltage needed for the spark plugs to ignite the fuel.

The Problem: On certain Audis and Volkswagens, the harnesses on the ignition coils can become brittle and cracked. When that happens, it can lead to engine misfires. With OE parts, you have to replace the entire harness, which is an expensive and time-consuming repair.

Our Response: TechSmart's Ignition Coil Harness Repair Kit allows you to repair the damaged portion of the ignition coil wiring instead of replacing the entire harness, saving you time and money in the process.

H11001

**Ignition Coil Harness
Repair Kit**
Audi/VW 2006-00
VIO over 280,000

Direct-fit replacement
part ensures ease
of installation

Properly restores
vehicle drivability and
ignition coil function

Terminal removal
tool included

Quality-engineered
replacement

Butt connectors
included



ARE YOU TECHSMART.®?

