THINK TECHSMART, FIRST

HVAC Air Door Actuators with Chamfered Pins

An HVAC Blend Door Motor/Air Door Actuator replacement can be a difficult and long install - up to 7+ hours. In most cases technicians are working in a confined area twisting and bending to install the actuator. Reconnecting the harness usually requires balancing the harness on fingertips, blindly trying to make the connection. TechSmart's chamfered pins allow technicians to reattach the harness easily, without the risk of damaging, bending, or snapping the pins; ensuring the job is done right the first time.



TechSmart® HVAC Air Door Actuators are engineered with chamfered pins for a better connector fit.




You don't want to do this job twice. TechSmart® HVAC Air Door Actuators with Chamfered Pins help you get it done right the first time.






Chamfered Pins



Competitor



Flat Pins

